Kopp/Denune Chronology

3/20/90

Palmer, Kleinhenz, Imhoff, Meyer, Angelopolous, Tammaro, and Haffenden inventoried the trailer at Welhem Junkyard and took samples.

EPA Region 5 Records Ctr. 254962

- 62 drum inventory sheets were filled out
- many more containers not inventoried
- Found labels with Dixie Distributing
- 10 samples were taken from containers of different sizes creating potential reaction (incompatibles stored next to each other -liquid fire had hole in container
- Samples #1 55-gallon drum WJ001 -liquid, (amber) Fl. Pt. greater than 95 degree C xylenes 10 mg/l
- Sample #2 55-gallon drum WJ002, gray sludge (waste)
- Fl. Pt. 35 degree-C
- Toluene 15. 0 mg/kg
- Ethyl Benzene 3400 mg/kg
- xylenes 24000 mg/kg
- -Sample #3 55-gallon drum WJ003, dark liquid PH=13
- Sample #4 5-gallon drum WJ063, yellow liquid PH less than 1
- Sample #5 10-gallon drum WJ054, dark liquid Fl pt. = 48 degree C
 Methylene Chloride 260 mg/l
 Toluene 470 mg/l
 xylenes 13,000 mg/l

- Sample 16 container of liquid lire i quart

- Sample #7 55-gallon drum WJ062 red liquid PH greater than 13
- Sample #8 55-gallon drum WJ027 liquid PH less than 1
- Sample #9 5-gallon drum WJ064 brown liquid Fl. Pt.
- Sample #10 40-gallon drum WJ024, whose condernot submitted cause possible cyanide labed as zinc cyanide.

SUMMARY OF RESULTS

Sample # 3&7 PH greater than 12.5 corrosive HW
Sample # 4,6,and 8 PH less than 1 corrosive HW
Sample 2,5 Fl.Pts. less than 60 degree C. Ignitable HW
Sample # 1 Fl.Pt. greater than 60 degree C. Not HW
Sample #10 labeled zinc cyanide - stored next to "liquid fire" container - incompatibles - potential reaction.

Shane, Pardi, Kotsko, Bryant, Johnson, O'Rourke, Wellman inventoried and sampled containers from the trailer at Wilhelm Sandblasting

INVENTORY RESULTS:

73 - 55-gallon drums 3 - 30-gallon drums 100 - 5 gallon pails 70 - 1 gallon buckets

Drums with HW or warning stickers scraped off

WS010 WS068

Drums with previous EPA numbers;

HD064 now WS028 HD007 now WS029 348 now WS080 142 now WS069

Containers with Dixie Distributing tags on them.

12 samples were taken.

11 from drums
1 from spilled material from drum WS074

SAMPLE RESULTS

Sample #1 55-gallon WS010, clear liquid, PH less than 1

Sample #2 5-gallon WS068, beige liquid Fl. Pt = 23 degree C

Methylene Chloride = 340 mg/l Toluene= 37,000 mg/l Ethyl benzene= 3,500 mg/l xylenes = 17,000 mg/l

```
Sample #3 55-gallon WS029, black liquid
Fl. Pt. greater than 95 degree C., small conc of organic
Sample #4 5 gallon WS069, F1. Pt. = 22 degree C, green liquid,
      2 butanone = 33,000 \text{ mg/kg}
      Toluene =
                        1000 \text{ mg/kg}
      Ethyl benzene = 20,000 mg/kg
                       87,000 mg/kg
      xylenes =
Sample #5 55-gallon WS028, dark brown liquid
      Fl.Pt = 31 degree C
      Methylene Chloride =
                                 .94 mg/1
      Acetone=
                                  47 \text{ mg/l}
      2 Butanone=
                                  7.4 \, \text{mg/l}
      Tetrachlorethene =
                                  1.8 \, \text{mg/l}
                                  2.5 \text{ mg/l}
      Toluene =
Sample #6 55-gallon WS067, brown liquid (waste)
Fl. pt. = 19 degree C
      Toluene =
                        210,000 mg/l
      ethyl benzene = 5,600 \text{ mg/l}
                        5500 mg/l
      styrene =
                        22,000 \text{ mg/l}
      xylenes =
Sample #7 55-gallon drum WS027, green liquid
      Fl.Pt. =34 degree C
      Toluene =
                                 320 \text{ mg/l}
      ethyl benezene =
                                 2200 mg/l
                                 1300 \text{ mg/l}
      styrene =
      xylenes =
                                 8900 \text{ mg/l}
Sample #8 leaked from WS074 5-gallon, silver waste
EP Toxic= barium 0.1 mg/l
Sample #9 5-gallon WS074, gray waste
Fl. Pt = 23 degree C.
      EP Tox metals =
                                 ND
                                640 mg/l
     Methyene Chloride =
                                 30,000 \text{ mg/l}
      Toluene =
      ethyl benzene =
                                 16,000 \text{ mg/l}
                                 78,000 \text{ mg/l}
      xylene
Sample # 10 55-gallon WS060, brown liquid
```

Fl. Pt. Top - not sufficient sample

Fl. Pt. Middle = 69 degree C

Top Toluene= 7,500 mg/l ethyl benzene = 410 mg/l xylenes = 2,000 mg/l

Middle acetone 1000 mg/l
2 butanone= 2.5 mg/l
Toluene= 3.8 mg/l
xylenes= 2.1 mg/l

Bottom F1. Pt. bottom - 57 degree C Solid Solid

ethyl benzene = 79 mg/kg styrene= 8.2 mg/kg xylenes 410 mg/kg methylene chloride= 2.3 mg/kg 1,2 Dichlorethane= 1.3 mg/kg Toluene = 1300 mg/kg

Sample # 11 55-gallon WS031, red brown liquid F1. Pt. less than 16 degree C

2-butanone = 67,000 mg/l Toluene = 180,000 mg/l Ethyl benzene = 1400 mg/l xylenes = 6700 mg/l

Sample # 12 55-gallon WS003, white liquid Fl. Pt. = 25 degree C

Toluene = 1700 mg/l ethyl benzene= 30,000 mg/l xylenes = 120,000 mg/l

SUMMARY OF RESULTS FROM (K900321-2) Wilhelm SandBlasting

Samples #1 PH less than 1 corrosive HW Samples # 2,4,5,6,7,9,11, and 12 Fl. Pt. less than 60 degree C. Large presence of Toluene, xylene, 2 butanone, ethyle benzene. Ignitable HW.

Sample #3 and 10 Fl.Pt. greater than 60 degree C, No HW for ignitability

Sample# 8 EP Tox below HW limits.

3/29/90

Palmer collected samples (soils) from under the 2 trailers to determine if soils were contaminated

(

- 1 sample from Liberty Rd.
- 2 samples from Lower Valley Pike

SAMPLE RESULTS

Sample #1 Liberty Rd. discolored soil, oil like
Solvent scan ND
PCB's ND
Sample # 2 Lower Valley Pike from leak in trailer, discolored
soil Solent scan ND
PCB's ND
Sample #3 Lower Valley Pike leak in trailer, tar like
Solvent scan 8.6 % xylene
0.7% naptha
PCB less than 2.5 ug/g